VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5401	D A T E	Nov.9. 2023		
MANUFACTURER	SUBARU CORPORATION				
DESCRIPTION OF DEFECT	Since the EGR pressure sensor mounted on the exhaust gas recirculation device (EGR) lacks resistance to exhaust gas, corrosion due to exhaust gas may cause the sensor output abnormally, turn the warning light on, cause acceleration failure, and in the worst case, the engine may not be able to start.				

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED		NUMBER OF VEHICLE
4BA-VN5	$\lceil ext{LEVORG} floor$	2020-	~2023	52,320
4BA-SK5	「FORESTER」	2020~2023		27,152
4BA-BT5	「LEGACY」	2021~2023		16,012
			TOTAL	95,484