

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5402	D A T E	Nov.9. 2023
MANUFACTURER	SUBARU CORPORATION		
DESCRIPTION OF DEFECT	In the front drive shaft, due to improper heat treatment in the manufacturing process, some outer races have cracks on the surface and lack strength. As a result, if the cracks progress during the use, the outer race could break, resulting in lack of motive power, in the worst case, the transfer clutch could be damaged, resulting in an inability to drive.		

T Y P E	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
5AA-GUE	「Crosstrek」	2023	70
5AA-GUE	「Impreza」	2023	25
3BA-GU7		2023	5
4BA-SK5	「Forester」	2023	28
5AA-SKE		2023	14
5BA-VBH	「WRX」	2023	27
4BA-BT5	「Outback」	2023	11
TOTAL			180