

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5406	DATE	Nov.9 2023
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some heavy-duty trucks equipped with a PDM (Power Distribution Module: fuse & relay box) on the left side of the driver's seat, the positive side wiring for the power supply of the PDM is incorrectly routed. Therefore, if the wiring is damaged due to interference with the PDM bracket and is short-circuited, there is a risk of vehicle fire in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-FV70GX	「FUSO SUPER GREAT」	2020~2022	168
2KG-FV70HJR		2020~2022	338
2KG-FV70HYP		2021~2022	40
2KG-FV70HZZ		2021~2022	13
2KG-FV74HJR		2020~2022	25
2PG-FP74GG		2021	1
2PG-FP74GGR		2020~2022	13
2PG-FP74HD		2021~2021	2
2PG-FP74HDR		2021~2022	599
2PG-FP74HER		2021~2022	230
2PG-FP74HGR		2021~2022	45
2PG-FS70HZ		2020~2022	184
2PG-FS74GY		2020~2022	11
2PG-FS74GZ		2020~2022	127
2PG-FS74HY		2020~2022	97
2PG-FS74HZ		2019~2022	4,661
2PG-FS75GY		2020~2022	5
2PG-FS75GZ		2020~2022	37
2PG-FS75HY		2020~2021	4
2PG-FS75HZ		2020~2022	820
2PG-FU70GY		2020~2022	82
2PG-FU70HY		2020~2022	112
2PG-FU74GY		2020~2022	72
2PG-FU74GZ		2020~2022	185
2PG-FU74HY		2020~2022	104
2PG-FU74HZ		2020~2022	1,682
2PG-FU75GZ		2020	1
2PG-FU75HZ		2022~2023	492
2PG-FV70GX		2020~2022	136
2PG-FV70GY		2020~2022	58
2PG-FV70GZ		2020~2022	17
2PG-FV70HX		2020~2022	1,021

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2PG-FV70HY	「FUSO SUPER GREAT」	2020～2022	294
2PG-FV70HZ		2020～2022	237
2PG-FV74GZ		2020～2022	45
2PG-FV74HJR		2020～2022	38
2PG-FV74HZ		2020～2022	364
2PG-FY70GY		2020～2022	6
2PG-FY70HY		2020～2022	95
2PG-FY74GY		2020～2022	32
2PG-FY74HY		2020～2022	156
2RG-FP74HD		2019～2019	2
2RG-FP74HDR		2020～2021	711
2RG-FP74HER		2020～2021	344
2RG-FP74HGR		2020～2021	56
		TOTAL	13,762