

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5419	DATE	Nov.22.2023
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	Due to inappropriate installation instructions for onboard tools, a parking brake release tool (spanner)is not installed. Therefore, if the parking brake remains operated due to a malfunction, etc., the brake cannot be released using the tool.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZBC-MUM1NAE	[SORA]	2018-2023	140
		TOTAL	140