VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

 CAMPAIGN No.
 5409
 DATE
 04 December 2023

 MANUFACTURE
 Hitachi Construction Machiney Co.,Ltd.
 DESCRIPTION OF DEFECT
 Improper assembly of EGR Valve used to recirculate the exhaust of the shovel loader installed engine may cause a cracking of EGR Valve, leading to exhaust leaks, and exhaust gas may fail to meet the emission standards.

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	REMARK
YDR-H86	۲ZW140-6J	2023	10	
		TOTAL	10	