

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5425	DATE	Dec.6.2023
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the transmission control computer (ECU) in the automatic transmission, due to improper maintenance of weld machine, there is a possibility that the weld of the ECU's case joint surface could be insufficient. If the vehicle is operated continuously in this condition, the transmission fluid could enter in the case, causing short circuit to occur by the metal powder in the fluid, and in the worst case, the vehicle may lose drive power while driving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-DB06	[SUPRA]	2023	3
3BA-DB26			9
3BA-DB86			6
		TOTAL	18