

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5424	D A T E	Dec.14. 2023
MANUFACTURER	SUBARU CORPORATION		
DESCRIPTION OF DEFECT	In the front drive shaft, due to improper heat treatment in the manufacturing process, some outer races have cracks on the surface and lack strength. As a result, if the cracks progress during the use, the outer race could break, resulting in lack of motive power, in the worst case, the transfer clutch could be damaged, resulting in an inability to drive.		

T Y P E	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
5AA-SKE	「Forester」	2023	74
4BA-SK5		2023	22
5BA-VBH	「WRX」	2023	15
3BA-GU7	「Impreza」	2023	13
5AA-GUE	「Crosstrek」	2023	8
4BA-BT5	「Legacy」	2023	3
TOTAL			135