

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	5428	DATE	December 18, 2023
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	In the case of the battery plug of a battery-powered forklift, due to insufficient design consideration, operator contact with the battery plug handle may cause the battery plug to misfit. And if used continuously in that state, there is a risk of heat generation from the terminal of the battery plug contact area, and in the worst case, it may lead to a fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAF-M283K	FE30-1	2016-2021	2
ZAF-M282K	FB20-12 FB25-12	2017-2023	151
ZAF-M282K	FE25-1	2016-2021	689
ZAF-M284K	FB30-12	2017-2023	9
ZAF-M284K	FE30-1	2016-2021	170
ZAF-M291	FE25H-1	2018-2021	203
TOTAL			1,224

Range of vehicles that may have been installed as replacement spare parts

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAF-M282K	FE25-1	2014-2016	5
ZAF-M284K	FE30-1	2016	1
TOTAL			6