## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

## Domestic Vehicles

CAMPAIGN No.	5455	DATE	Feb.21.2024		
MANUFACTURER	ТОУОТА				
DESCRIPTION OF DEFECT	#1. In an automatic transmission, due to insufficient consideration of the disc design of the multi-plate clutch and the control of the drive transmission, the clutch may not be disengaged when shifting to the neutral range.  Therefore, the driving force is transmitted, and if the brake pedal is not applied, the vehicle may start moving.				
	#2. In a Panoramic View Monitor system, due to an improper programming, there is a possibility that the camera image may not be displayed, and the surrounding area of the vehicle cannot be provided. This condition would not meet requirement prescribed in "Safety Regulations for Road Vehicles", Article 44 (Rearview mirror).				

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF	NOTE
	NAME	RECALLED	VEHICLE	
3DA-FJA300W	[LAND CRUISER]	2021-2024	7,528	#1
3BA-VJA300W		2021-2024	19,962	#1
4BA-MXGA10	[COROLLA CROSS]	2023	377	#2
3BA-VJA310W 3BA-VJA310W "kai"(modified)	[LX600]	2021-2022	1,346	#1 and #2
3BA-VJA310W		2022-2024	3,735	#1
		TOTAL		32,948

#1: 32,571

#2: 1,723

#1 and #2: 1,346