VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5457	DATE	Feb.22 2024		
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation				
DESCRIPTION OF DEFECT	On some light-duty buses, the brake lamp switch is assembled with the push rod protrusion less than the specified value due to incorrect assembly instructions. As a result, the brake lamps may not turn on when the amount of depression of the brake pedal is small. In addition, if this occurs while the hill start assist device (EZGO) is activated, the ECU may incorrectly determine that the system is in an abnormal state, causing the collision damage mitigation brake (AEBS) and vehicle behavior stabilizing (ASR) systems to stop functioning and the warning lamp to turn on.				

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED		NUMBER OF VEHICLE
2RG-BE740E		6	2019~2023	420
2RG-BE740G	「FUSO ROSA」	2019~2023		1,708
2RG-BE740J		2019~2023		322
2RG-BG740G		2019~2023		533
			TOTAL	2,983