

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5465	DATE	March 28, 2024
MANUFACTURER	DAIHATSU		
DESCRIPTION OF DEFECT	<p>In some replacement part sets for repairing the rear shock absorber, bolts that are shorter than the original were mistakenly included.</p> <p>If the shorter bolts are used during replacement, they may loosen while driving due to vibration, etc. causing abnormal noise.</p> <p>In the worst case, the bolt may loosen until it becomes completely unscrewed resulting in the stability of the vehicle to become impaired.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
5BA-LA850S	MOVE CANBUS	2022-2023	19
5BA-LA860S			4
		TOTAL	23