

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	5472	DATE	April 5, 2024
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	In battery-powered forklifts equipped with heaters, the heater power harness connectors are inserted with the terminals reversed due to improper insertion. Since the terminals do not contact each other properly, the electrical resistance of the contact portion increases, and if the heater continues to be used as it is, there is a risk that the terminals will generate heat and the connector will burn out.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAF-M299	FE25-2 FE30-2	2021-2024	36
ZAF-M304	FE25G-2	2023	1
TOTAL			37