

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

## Domestic Vehicles

CAMPAIGN No.	5478	DATE	May.8.2024
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the light control computer, the lighting control program was designed incorrectly, therefore the front position lamps do not operate properly even they designed to turn on/off to synchronize with other lights when the direction indicators lamps or hazard warning lamps are operated. This condition will not meet requirement prescribed in “Safety Regulations for Road Vehicles”, Article 34 (Front position lamps).		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
6BA-MZRA90W	[NOAH] [VOXY]	2024	505	Reflector type headlight
6BA-MZRA92W			30	
6BA-MZRA95W			108	
6AA-ZWR90W			494	
6AA-ZWR95W			95	
6BA-MZRA97W	[NOAH]		8	
6AA-ZWR92W			7	
6BA-MZRA90C	[LANDY]		3	
6AA-ZWR90C			16	
6AA-ZWR95C			5	
		TOTAL	1,271	