

# VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

|                       |   |      |               |
|-----------------------|---|------|---------------|
| CAMPAIGN No.          | 5479  | DATE | 14. May. 2024 |
| MANUFACTURER          | YAMAHA MOTOR CO., LTD.  |      |               |
| DESCRIPTION OF DEFECT | Regarding the cable for transmitting speeds, which is installed to the speedometer ASSY, the setting for the clearance between the speedometer and the wire in the cable is not suitable. Because of this, there are cases where the clearance becomes small as the dimension of the cable changes due to bending of the cable while the vehicle is used. Consequently, if the vehicle continues to be used, the clearance becomes zero, and the speedometer and the wire in the cable contact, and in the worst case, the speedometer may not show correct speeds. |      |               |

| TYPE      | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|-----------|-----------------|---------------------|-------------------|
| 2BJ-SED7J | AXIS Z LTS125   | 2017～2021           | 39,808            |
| 8BJ-SEJ6J | AXIS Z          | 2021～2022           | 4,680             |
| TOTAL     |                 |                     | 44,488            |