

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5481	DATE	May 21, 2024
MANUFACTURER	Trantechs, Ltd.		
DESCRIPTION OF DEFECT	In wing bodie tracks, due to improper manufacturing control of the routing points of the wing power harness, the wing power harness may press against the chassis harness and the unprotected part of the chassis harness may interfere with the chassis frame. As a result, the covering of the chassis harness may break and short-circuit due to driving vibration, etc., and in the worst case, the engine may stop, resulting in a fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2PG-FRR90S1 2PG-FRR90S2 2PG-FRR90S4 2PG-FRR90T2 2PG-FRR90T4 2RG-FRR90S1 2RG-FRR90S2 2RG-FRR90S3 2RG-FRR90S4 2RG-FRR90T2 2RG-FRR90T4	Forward	2017～2024	830	
2PG-FTR90V2 2RG-FTR90U2 2RG-FTR90U4 2RG-FTR90V2 2RG-FTR90V4		2018～2024	199	
2PG-FSR90S2 2PG-FSR90T2 2PG-FSR90T4 2RG-FSR90S2 2RG-FSR90S4 2RG-FSR90T2 2RG-FSR90T4		2017～2024	126	
2KG-FVZ60U2		2019～2023	17	
2PG-FVR90U2		2018～2021	8	
2PG-BRR90T2 2RG-BRR90S1 2RG-BRR90S2 2RG-BRR90T2		2018～2023	68	
2PG-BSR90T2 2RG-BSR90S2 2RG-BSR90T2		2020～2023	28	
2PG-BTR90V2 2RG-BTR90U2 2RG-BTR90V2		2018～2023	19	
		TOTAL	1,295	