

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5 4 8 5	DATE	May. 30. 2024
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	In some drive motors, the O-ring for oil seal was damaged at the time of assembly because the jig to mount the bearing was inadequate. Therefore, the cooling oil in the drive motor leaks from the relevant part in the process of using. And the insulation resistance decreases, and in the worst case, the output of the drive motor may be stopped, and it may lead to be unable to drive.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
Z A A - F E 0	A R I Y A	2 0 2 2 ~ 2 0 2 3	6 6
Z A A - S N F E 0		2 0 2 2	1
		TOTAL	6 7