

VEHICLE SAFETY／POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic／Import Vehicles

CAMPAIGN No.	5463	DATE	2024/06/06
MANUFACTURE	Niigata Transsys co.ltd.		
DESCRIPTION OF DEFECT	In a rotary snowplow, the vehicle were shipped without the pressure switch for the low charge pressure warning light set due to improper confirmation during shipping inspection. Therefore, if the charge pressure decreases while driving on the road, the warning light will not light up properly, and in the worst case, there is a risk that driving force will not be transmitted and the vehicle will be unable to travel.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
-	NR43	2015～2023	168
		TOTAL	168