VEHICLE SAFETY / POLLUTION RECALL CAMPAINGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	5490	DATE	june. 13.	2024	
MANUFACTURE	Topre Corporation				
DESCRIPTION OF DEFECT	Some large vehicles with refrigerator, instruction of the frontmost left side U-bolt that fastens the chassis frame and subframe was inappropriate, resulting in a narrow gap between the chassis wiring and the U-bolt. If the customer continues to use the vehicle in this condition, there is a possibility that the wiring will be rubbed due to vibrations during driving, causeing electlic short circuit. In the worst case, the engine may stall while driving. We will inspect all vehicles, and if the wiring is damaged, we will repair the wiring and, relocate the U-bolt from its current position to back.				

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2KG-FS74HZ	FUSOSUPERGREAT	2021~2023	32	
2KG-FU74HZ		2021~2023	6	
2PG-FS74GY		2018~2022	12	
2PG-FS74GZ		2020	3	
2PG-FS74HY		2017~2023	12	
2PG-FS74HZ		2017~2024	309	
2PG-FS75GY		2022	2	
2PG-FS75HZ		2017~2024	197	
2PG-FU74GZ		2018~2020	2	
2PG-FU74HY		2018~2023	11	
2PG-FU74HZ		2017~2024	115	
2PG-FU75HZ		2017~2024	33	
2PG-FV74HZ		2019~2023	10	
		TOTAL	744	