

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5497	DATE	Jun.14.2024
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In a Panoramic View or Back Guide Monitor system, due to improper maintenance of welding machine, there is a possibility that waterproof of the camera case may be insufficient, resulting in allowing water to leak into the camera. If this occurs, the circuit inside the camera can short, leading to an inability to display an image of the surrounding area of the vehicle.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
6BA-MZRA90W	[NOAH] [VOXY]	2023	6,636	
6BA-MZRA92W			150	
6BA-MZRA95W			959	
6AA-ZWR90W		2022-2023	73,847	
6AA-ZWR92W			451	
6AA-ZWR95W			13,259	
6BA-MZRA95W “Kai”(modified)	[NOAH]	2023	6	
6BA-MZRA97W			9	
6AA-MXWH60	[PRIUS]	2022-2023	32,649	
6LA-MXWH61		2023	4,573	
6AA-MXWH65		2022-2023	7,129	
6AA-ZVW60			2,804	
6AA-ZVW65			557	
5BA-MZEA17W	[COROLLA TOURING]	2023	2,837	
6AA-ZWE215W			3,888	
6AA-ZWE219W			13,214	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
6AA-AZSH35	[CROWN]	2023	14,540	
5AA-TZSH35			3,754	
5BA-MXPC10G	[SIENTA]		2,125	
5BA-MXPC12G			73	
6AA-MXPL10G			11,909	
6AA-MXPL12G			125	
6AA-MXPL15G			2,517	
ZBA-JPD20	[MIRAI]		188	
ZAA-XEAM10	[bZ4X]		68	
ZAA-YEAM15			51	
5BA-TALA10	[RX350]	2022-2023	504	
5BA-TALA15			3,058	
6AA-AALH10	[RX350h]	2023	117	
6AA-AALH15			69	
6LA-AALH16	[RX450h+]	2022-2023	2,385	
5AA-TALH17	[RX500h]		7,509	
5BA-AAZA20	[NX250]		1,920	
5BA-AAZA25			283	
5BA-TAZA25	[NX350]		322	
6AA-AAZH20	[NX350h]		4,675	
6AA-AAZH25			1,976	
6LA-AAZH26	[NX450h+]		1,176	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
6BA-MZAA10	[UX200]	2023	326	
6AA-MZAH10	[UX250h]		5,852	
6AA-MZAH15			1,139	
ZAA-KMA10	[UX300e]		112	
3BA-VXFA50	[LS500]	2022-2023	413	
3BA-VXFA55			121	
6AA-GVF50	[LS500h]		645	
6AA-GVF55			705	
6AA-AXZH11	[ES300h]	2023	1,627	
3BA-VJA310W	[LX600]		1,615	
ZAA-XEBM15	[RZ450e]		19	
ZAA-XEAM10X	[SOLTERRA]		30	
ZAA-YEAM15X			161	
		TOTAL	235,077	