

# VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	5501	DATE	June 24, 2024
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	In some hydraulic oil tank breathers of shovel loaders, the dimensions of the groove that secures the cover to the case were inadequately controlled. Consequently, gaps have occurred between the bayonet (resin) of the case and the bayonet (aluminum) of the cover. As a result, the O-ring cannot sufficiently fill the gap. If the bayonet continues to be used as it is, hydraulic oil may leak due to internal pressure in the hydraulic oil tank.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDN-WA139	「WA80-8」	2022~2023	465
YDP-WA138	「WA100-8」	2022~2023	994
YDP-WA138	「WA150-8」	2022~2023	225
YDR-WA137	「WA200-8」	2022~2023	336
TOTAL			2050

Models of vehicles that may be used as service parts

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SB-W108	「WA100-5」	2004-2007	2
KDP-WA115	「WA100-6」	2011-2013	5
WDP-WA124	「WA100-7」	2017	1
YDP-WA138	「WA100-8」	2018-2020	4
KDP-WA115	「WA150-6」	2013	1
YDP-WA138	「WA150-8」	2021	1
EDR-WA105	「WA200-6」	2012	2
WDR-WA126	「WA200-7」	2014	1
YDR-WA137	「WA200-8」	2019	1
EDR-WA103	「WA270-6」	2011	1
EDR-WA108	「WA320-6」	2012-2013	2
TOTAL			21