

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5500	DATE	Jun. 27 2024
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	In the exhaust brake of some trucks equipped with a 4V20 engine, the exhaust brake drive gear may hit the stopper at a speed faster than expected due to an inappropriate control program in the engine ECU. If this repeatedly occurs, the exhaust brake drive gear and the intermediate gear will be damaged, causing the exhaust brake to become inoperative and the engine control warning light to come on.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2PG-FK62N	「FUSO FIGHTER」	2019～2023	93
2PG-FK62NA		2019～2022	10
2PG-FK65N		2019～2023	27
2PG-FK65NA		2019～2023	23
2PG-FK72N		2019～2024	1,183
2PG-FK72NA		2019～2023	35
2PG-FK75N		2019～2023	62
2PG-FK75NA		2020～2022	2
		TOTAL	1,435