

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/ Vehicles

CAMPAIGN No.	5517	DATE	Jul. 11th, 2024
MANUFACTURER	Yokohama Sharyo Kogyo Co.,Ltd.		
DESCRIPTION OF DEFECT	In a large tractor coupling device, the shape of the lock guard to prevent incorrect coupling is inappropriate, so if the coupling operation is performed when the tractor and trailer are not at the same height, the lock guard will not function properly, resulting in an incorrect coupling, and the coupler lock lamp in the vehicle's meter, which indicates that the coupling is complete, may light up. Therefore, if you continue to use the device without visually checking the coupling status, there is a risk that the tractor and trailer will separate while driving.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-FV70HJR	FUSO SUPER GREAT	2021	18
2PG-FP74HD	FUSO SUPER GREAT	2021	1
		TOTAL	19

The range of vehicles shipped and installed as replacement repair parts

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QDG-FV50VJR	FUSO SUPER GREAT	2012	2
QDG-EXZ52AJ	GIGA	2014. 6	1
QDG-EXZ52BJ	GIGA	2015	1
		TOTAL	4