

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5521	DATE	July. 11. 2024
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	As for the motor, some paint may be found on its press-fitted pipe joint due to improper manufacturing process of the water pump cover. For this reason, the heat of the engine and other parts may reduce the tightening margin of the press-fitted pipe joint, causing the joint pipe to fall out and high-temperature coolant to leak. In the worst-case scenario, the rider may get burned by touching the coolant or the engine may be burned out.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
8BK-MC51	「CBR250RR」	2022～2023	3,191
TOTAL			3,191

The affected parts shipped as repair parts, but the vehicles with them installed, cannot be identified.

PARTS	PART No.	DELIVERED AS “SERVICE PARTS”	NUMBER OF PARTS	NOTE
PUMP ASSY., WATER	19200-K64-NA0	2023～2024	59	「CBR250RR」
TOTAL			59	