VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5512	DATE	July 18, 2024	
MANUFACTURER	SUZUKI MOTOR CORPORATION			
DESCRIPTION OF DEFECT	Due to poor management of manufacturing process, some ignition coils were assembled with wrong high-tension cords. If the vehicle continues to be used, the high-tension cord may crack due to repeated bending, and in the worst case, the wire may break, causing the engine to stop, and the engine cannot be restarted. In addition, if a cracked high-tension cord gets water, the ignition output leaks and the vehicle speed sensor and the throttle position sensor are damaged, causing a vehicle speed display failure, an			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
8BJ-DP12H	ADDRESS 125	2022 - 2023	1,244
8BJ-EA12J	AVENIS 125	2022 - 2023	942
		TOTAL	2,186