

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5519	DATE	July 18, 2024
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	Due to inadequate control programs in the combination meters, the warning labeling time to signal that the backseat seat belt is not worn at the time of vehicle start-up or engine start-up may not meet the display time specified by the law. Therefore, it does not comply with Article 22-3 of the Safety Standard (seat belts, etc.).		

T Y P E	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
5LA-GN0W	「OUTLANDER PHEV」	2021～2024	34,756
3DF-LC2T	「TRITON」	2024	1,167
		TOTAL	35,923