

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles			
CAMPAIGN No.	5524	DATE	July 30, 2024
MANUFACTURER	Mazda E&T Co.,Ltd.		
DESCRIPTION OF DEFECT	In some diffuse-type warning lights installed on roadwork vehicles, grease is not applied to the switch contacts due to an improper manufacturing process for the power switch. Therefore, repeated operation of the switch may cause the light to turn off while it is on due to conduction failure in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3DA-KG2P	Mazda CX-8	2024	2
6BA-KG5P	Mazda CX-8	2024	1
TOTAL			3