

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/ Import Vehicles

CAMPAIGN No.	5527	DATE	Jul. 31. 2024
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain electric wiring of medium-duty trucks, due to insufficient design examination of the wiring dispersion, there are cases in which the wiring of the left frame part and peripheral parts such as the engine side cover interfere with each other. Therefore, if it is used continuously, the insulation of the wiring may be damaged by vibration and so on while operating, causing a fire due to a short circuit of the wiring in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2DG-FD2ABA 2KG-FD2ABA 2KG-FD2ABG 2KG-FD2ABJ 2PG-FD2ABA 2PG-FD2ABG 2PG-FD2ABJ	[HINO Ranger]	2017～2021	25, 580
2DG-FE2ABA 2KG-FE2ABA 2KG-FE2ABG 2PG-FE2ABA 2PG-FE2ABG		2017～2021	7, 674
2DG-GD2ABA 2KG-GD2ABA 2KG-GD2ABG 2PG-GD2ABA 2PG-GD2ABG		2017～2021	2, 503
		TOTAL	35, 757