VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5533	DATE	September. 5. 2024		
MANUFACTURER	HONDA MOTOR CO., LTD.				
DESCRIPTION OF DEFECT	Because of the inappropriate water-proof structure of the front and rear wheel speed sensor, water may penetrate into the sensor sometimes when riding in the rain, for example. This has the risk of shorting the sensor circuits, making the wheel speed signals unstable causing the incorrect speedometer indication, or activating traction control causing insufficient acceleration. In the worst-case scenario, the sensor has the risk of incorrectly detecting that the wheel was locked while running, which disables the brake.				

TYPE	COMMERCIAL NAME	MODEI RECA	L YEAR LLED	NUMBER OF VEHICLE
2BL-NC59	「GB350」	2021~2022		17,151
8BL-NC59	「GB350 S」	2023~	~2024	7,861
			TOTAL	25,012