

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5540	DATE	September 20, 2024
MANUFACTURER	DAIHATSU		
DESCRIPTION OF DEFECT	Due to inadequate tightening of the bolts in the front seat, some of the bolts may become loose due to vibration during driving. As a result, abnormal noise may occur from the tightening area, and if it continues to be used, the bolts may come off. In the worst case, the seat may move in the event of a collision, compromising its occupant protection performance.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
5BA-LA650S 6BA-LA650S	TANTO	2019-2023	310,968
5BA-LA660S 6BA-LA660S			85,370
5BA-LA900S 6BA-LA900S	TAFT	2020-2023	159,044
5BA-LA910S 6BA-LA910S			48,364
5BA-LA350S	Mira e:s		164,410
5BA-LA360S			32,896
5BA-LA800S	MOVE CANBUS	2019-2022	100,335
5BA-LA810S			22,771
5BA-LA850S		2022-2023	50,191
5BA-LA860S			10,327
DBA-LA150S 3BA-LA150S 5BA-LA150S	MOVE	2020-2023	100,532
DBA-LA160S 3BA-LA160S 5BA-LA160S			22,856
5BA-A200S	ROCKY	2019-2021	39,579
5BA-A201S		2021-2023	11,296
5AA-A202S			23,223
5BA-A210S 3BA-A210S		2019-2023	22,261

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-LA250S 3BA-LA250S 5BA-LA250S	CAST	2020-2023	44,338
DBA-LA260S 3BA-LA260S 5BA-LA260S			6,941
DBA-LA550S 5BA-LA550S	Mira TOCOT		23,739
DBA-LA560S 5BA-LA560S			4,536
5BA-A200A	RAIZE	2019-2021	155,743
5BA-A201A		2021-2023	60,198
5AA-A202A			56,956
5BA-A210A 3BA-A210A		2019-2023	74,234
5BA-LA350A	PIXIS EPOCH	2020-2023	21,422
5BA-LA360A			5,304
DBA-LA250A 3BA-LA250A 5BA-LA250A	PIXIS JOY		10,527
DBA-LA260A 3BA-LA260A 5BA-LA260A			1,991
5BA-LA650F 6BA-LA650F	CHIFFON	2019-2023	11,435
5BA-LA660F 6BA-LA660F			5,103
DBA-LA150F 5BA-LA150F	STELLA	2020-2023	7,365
DBA-LA160F 5BA-LA160F			3,549
5BA-LA350F	PLEO PLUS		7,649
5BA-LA360F			2,926
5BA-A201F	REX	2022-2023	2,228
		TOTAL	1,710,607