

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles			
CAMPAIGN No.	5541	DATE	Sep.26 2024
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	In some heavy-duty touring buses, the adhesion between the reinforcing cords and the base rubber in retarder hoses and radiator hoses is insufficient due to an inappropriate reinforcement method. Therefore, if the reinforcing cords wear down and break due to pressure fluctuations of the coolant inside the hoses, the hoses may break and cause coolant leakage.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2TG-MS06GP	「FUSO AERO ACE」	2017～2023	2,244
	「FUSO AERO QUEEN」	2017～2023	373
	TOTAL		2,617