

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5 5 3 9	D A T E	Oct.1.2024
MANUFACTURER	K i r y u - K o u g y o C o . , L T D .		
DESCRIPTION OF DEFECT	In the diffused warning lights installed in vehicles used for road maintenance work do not have grease applied to the switch contacts due to an inappropriate manufacturing process for pull-out switches for vehicles. Therefore, if the switch operation is repeated, there is a risk that the diffused warning light may turn off while it is on or become unable to dim due to poor conduction		

T Y P E	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
4BA－SK5	「FORESTER」	2023	3
5AA－SKE		2023－2024	6
		TOTAL	9