

# VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	5544	DATE	October 2, 2024
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	<p>Due to assembly instructions for the internal components of the gas spring being incorrect, some of the steering posts of the grader were assembled in a way that resulted in them touching the push valve and bracket.</p> <p>As a result, the push valve may be pushed by vibrations during operation, causing the internal lock of the gas spring to malfunction.</p> <p>In addition, some gas springs do not have a sufficient number of washers inside the piston, which may cause oil inside the piston to leak due to vibrations during operation.</p> <p>As a result, the steering post may not be secured if the gas spring continues to be used as it is.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDS-GD032	「GD675-6」	2023-2024	79
TOTAL			79