

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5542	DATE	October 3, 2024
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	<p>The fuel pump may crack the surface of the plastic outlet port when used in an environment subjected to chloride attack because of the inadequate connection structure to the fuel hose. If it is used continuously for a long time under this condition, the crack may extend and the fuel may leak.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
JBK-CH41A	BURGMAN	2014-2017	4,728
2BK-CH41A	BURGMAN	2017-2022	7,077
		TOTAL	11,805