

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5 5 4 6	DATE	Oct. 3. 2024
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	Some roof trims are thicker than standard due to improper setting of molding equipment. Therefore, there is a possibility that the curtain airbag mounted on the back side of the roof trim will not deploy normally.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
6 AA-GFC 2 8	S E R E N A	2 0 2 3	1 8 0
6 AA-GC 2 8			1 2
5 BA-FC 2 8			3
5 BA-FNC 2 8			1
5 BA-C 2 8			1
		TOTAL	1 9 7