

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	5547	DATE	October 9, 2024
MANUFACTURER	ISEKI & CO., LTD.		
DESCRIPTION OF DEFECT	Due to improper molding process, the connecting part of the fuel return hose may crack, which may lead to fuel leakage.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
T280F	TM197	2024	5
T281F	TM177	2023-2024	38
		TOTAL	43