

# VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	5551	DATE	October 10, 2024	
MANUFACTURER	UD Trucks Corporation			
DESCRIPTION OF DEFECT	With regards to the propeller shaft for heavy duty tractors, due to the inappropriate operation for welding the yolk shaft and tube, some of the weld penetration in the area in question are insufficient. Thus, cracks occur in welds when subjected to repeated stress in the process of use, if the product continues to be used as is, it may rupture or separate, resulting in loss of power transmission and driving inoperability.			
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2PG-GK5AAB	Quon	2022	259	
		TOTAL	259	