

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5553	DATE	October. 10. 2024
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	As for some hybrid vehicles, due to the inappropriate working process of the high-pressure fuel pump components, metallic powder created in the process may get stuck between the pump component and the working jig. This could cause a crack on the end of the worked part and the continuation of use may make the crack completely run through due to the oscillation of the operating pump, resulting in a fuel leakage.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
6AA-RZ4	「ZR-V」	2022～2024	35,739
6AA-RZ6			16,322
6AA-FL4	「シビック」		10,783
		TOTAL	62,844

The affected parts shipped as repair parts, but the vehicles with them installed, cannot be identified.

PARTS	PART No.	DELIVERED AS “SERVICE PARTS”	NUMBER OF PARTS
PUMP ASSY.,FUEL HIGHT PRESSURE	16790-6MA-J01	2022～2024	22
		TOTAL	22