

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5561	DATE	October.23.2024
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	Due to inadequate management for the welding equipment, the welding strength of the mounting brackets on the rear seat leg may be insufficient. As a result, the welds may separate while in use, causing looseness, and in the worst case, the occupants may not be protected at the time of a collision.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
3DF-GDH201V	[HIACE]	2023	173	Super GL grade
3DF-GDH206V			345	
3DF-GDH211K			33	
3BF-TRH200V			92	
3BF-TRH211K			14	
3BF-TRH216K			31	
		TOTAL	688	