

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5570	DATE	October. 31. 2024
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	As for the motor, due to the inappropriate management method in the process of manufacturing the crankcase and the gearbox casing, both cases may not adhere to each other tightly enough, causing a transmission oil leakage. For this reason, poor oil lubrication may make an odd noise and if it continues to be used, a bearing inside one of the cases may be damaged and in the worst case, the rear wheel may be locked up while running, becoming unable to run.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
JBH-AF79	「TACT」	2016～2017	61,698
2BH-AF79		2017～2024	186,981
JBH-AF77	「Giorno」	2015～2017	26,292
2BH-AF77		2017～2024	60,900
JBH-AF78	「Dunk」	2016～2017	6,950
2BH-AF78		2017～2024	26,485
2BH-AY01	「JOG」「JOG Deluxe」	2018～2024	160,400
2BH-AY02	「Vino」	2018～2024	69,091
		TOTAL	598,797