VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5571	DATE	October. 31. 2024		
MANUFACTURER	HONDA MOTOR CO., LTD.				
DESCRIPTION OF DEFECT	As for the motor, due to the insufficient durability of the bolt securing the drive gear to the crankshaft, excessive stress may concentrate on the bolt at the time of aggressive acceleration, causing cracks on the bolt. For this reason, if it continues to be used, the bolt may break, causing the pulse rotor that detects the crankshaft revolution to come off, resulting in an engine failure because of the inappropriate performance of ignition and fuel injection. In the worst case, the broken pieces of the bolt may get caught in the gear, locking up the engine.				

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED		NUMBER OF VEHICLE
2BL-SC79	「Gold Wing」 「Gold Wing Tour」	2018~2021		2,041
			TOTAL	2,041