

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5564	DATE	2024/11/5
MANUFACTURER	KUBOTA Corporation		
DESCRIPTION OF DEFECT	Due to insufficient design against water ingress and vibration in the holder attached to the steering controller of agricultural tractors, rust develops on the spline connected to the holder after prolonged use, leading to wear. Therefore, if usage continues as is, the wear on the splines may progress, and in the worst case, the steering may become free-spinning, making steering operation impossible.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
-	「MR1000A」 「MR1000A—PC」	2019～2023	77
	「MR1000AH」 「MR1000AH—PC」	2021～2024	171
		TOTAL	248

[Notes]

The range of vehicle numbers for recalled vehicles may include vehicles that are not.