

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5576	DATE	Nov.21.2024
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the aluminum wheels, due to improper parts management in the manufacturing process, the prototype wheels without the vehicle indication marking which were manufactured during development were installed to some vehicles. In this condition, the subject vehicles may not meet a certain requirement prescribed in “Safety Regulations for Road Vehicles”, Article 9 (Standards for Running Device).		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
5BA-URZ100	[LC500]	2023-2024	566	
6AA-GWZ100	[LC500h]		99	
		TOTAL	665	

The affected parts shipped as repair parts, and could not possibility the vehicles equipped with them.

PARTS NAME	PARTS NO.	SHIPMENT YEAR	NUMBER OF PARTS
Aluminum Wheel	4261A-11050	2023-2024	5
	4261A-11060		19
		TOTAL	24