## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

## Domestic Vehicles

CAMPAIGN No.	5577	DATE	Nov.21.2024		
MANUFACTURER	TOYOTA				
DESCRIPTION OF DEFECT	In the intermediate shaft, due to insufficient consideration during the forging process, cracks may occur when forging the joint part. As a result, these cracks may propagate and lead to breakage during use, potentially causing a loss of steering control in the worst-case scenario.				

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF	NOTE
	NAME	RECALLED	VEHICLE	
6AA-ZVW60	[PRIUS]	2023	2,652	
6AA-ZVW65	-		415	
5BA-MZEA17	[COROLLA]		296	
6AA-ZWE215			80	
6AA-ZWE219	-		236	
5BA-MZEA17W	[COROLLA TOURING]		496	
6AA-ZWE215W			243	
6AA-ZWE219W	-		484	
	•	TOTAL	4,902	