

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	5578	DATE	November 21, 2024
MANUFACTURE	TOYOTA INDUSTRIES CORPORATION		
DESCRIPTION OF DEFECT	With the welded parts of the overhead guard, which is a component of the frame of electric forklift vehicles, there are ones that may not fulfill enough strengths due to insufficient design consideration. In case of applying excessive stress to the part repeatedly, there is a possibility that it may cause the welded part to get cracked. Moreover, in case of continuing to use the forklift vehicle with the cracked welded part of the overhead guard, there is a possibility that it may cause the welded part to get fractured and the component of the overhead guard to fall off.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAF-8FBE13	TOYOTA GENEO-E	2015 - 2024	787
ZAF-8FBE18		2015 - 2024	2,383
ZAF-8FBE20		2015 - 2024	534
		TOTAL	3,704