VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5582	DATE	Nov.21.2024
MANUFACTURER	ТОҮОТА		
DESCRIPTION OF DEFECT	In a Panoramic View or Back Guide Monitor system, due to improper maintenance of welding machine, there is a possibility that waterproof of the camera case may be insufficient, resulting in allowing water to leak into the camera. If this occurs, the circuit inside the camera can short, leading to an inability to display an image of the surrounding area of the vehicle.		

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF	NOTE
	NAME	RECALLED	VEHICLE	
5BA-MZEA17W	[COROLLA	2023	225	
	TOURING			
6AA-ZWE215W			287	
6AA-ZWE219W			917	
		TOTAL	1,429	

The affected parts shipped as repair parts, and could possibility the vehicles equipped with them.

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF VEHICLE
	NAME	RECALLED	
5BA-MZEA17W	[COROLLA TOURING]	2023	2
6AA-ZWE215W		2022-2023	4
6AA-ZWE219W		2022-2024	7
6AA-ZWR90W	[NOAH] [VOXY]	2022-2023	5
		TOTAL	18