

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5583	DATE	Nov.21.2024
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	Due to insufficient production facility management, certain components for the wheel side joint of drive shaft may not installed on the vehicle. If the vehicle continues to be driven with this condition, the joint may be broken, resulting in the vehicle becoming inoperative.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
3DA-GDJ250W	[LAND CRUISER]	2024	725	
3BA-TRJ250W			626	
		TOTAL	1,351	