

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5580	DATE	Nov 22nd, 2024
MANUFACTURER	KUBOTA Corporation		
DESCRIPTION OF DEFECT	Due to improper tension adjustment of the fan belt on the agricultural tractor, there is a risk of over-tensioning, which could lead to damage to the fan belt. As a result, the dynamo may not operate, causing the battery charge warning light to illuminate. If the tractor continues to be used in this condition, there is a possibility that the engine could overheat, leading to engine seizure and rendering the vehicle inoperable.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BP	「JB17X」	KBUBADDRHN1F22036 ~ KBUBADDRVP1H22087 Jun 22nd, 2022 ~ Aug 18th, 2023	43
—	「GFK17」	KBUBADDRTN1H22046 ~ KBUBADDRJP1G22083 Aug 8th, 2022 ~ Jul 19th, 2023	9
BQ	「JB19X」	KBUBAEDRJN1F17000 ~ KBUBAEDRAP1H18287 Jun 9th, 2022 ~ Aug 24th, 2023	279
—	「JB18X」	KBUBAEDRCN1F17001 ~ KBUBAEDRAP1H18290 Jun 9th, 2022 ~ Aug 24th, 2023	1012
		TOTAL	1343

[Notes]

The range of vehicle numbers for recalled vehicles may include vehicles that are not.