

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5589	DATE	Nov. 28,2024
MANUFACTURER	DAIHATSU		
DESCRIPTION OF DEFECT	In the rear combination lamp of the dump truck, the design of the lamp placement was inappropriate. As a result, ice or snow kicked up by the rear wheels would accumulate onthe seal behaind the lamp and form chunk. If the vehicle continues to be used in this condition, the seal may deform, allowing water to seep into the lamp, causing the tail light and brake light to stay on all the time or not light at all.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BD-S510P	HIJET TRUCK	2021-2023	5,083
TOTAL			5,083