VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5590	DATE	Dec.5.2024	
MANUFACTURER	TOYOTA			
DESCRIPTION OF DEFECT	In the AHS* of the driver to insufficient considerate which controls the intension possibility that AHS companients abnormality when switching occurs, the warning mess become inoperative. * Adaptive High Beam forward visibility by consurrounding circumstance.	tion of programming in sity distribution of the aputer may incorrectly dang from the low beam to age will be displayed, and System: The system hele trolling high beam distribution of the programming in the system is the system of the system is the system in the system in the system is the system in the system is the system in the system in the system in the system is the system in the system in the system is the system in the system in the system in the system is the system in the system in the system in the system is the system in the system in the system in the system is the system in the system in the system is the system in the system in the system in the system is the system in the system in the system in the system is the system in the system in the system in the system is the system in the system in the system in the system is the system in the system in the system in the system is the system in the system in the system in the system is the system in the system in the system in the system is the system in the system is the system in the system	the AHS computer headlamp, there is a etect the signal as an the high beam. If this had the high beam will ps to ensure driver's ibution depending on	

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF	NOTE
	NAME	RECALLED	VEHICLE	
6BA-MXUA80	[HARRIER]	2023	3,977	with AHS
6BA-MXUA85			498	
6AA-AXUH80			5,604	
6AA-AXUH85			1,908	
6LA-AXUP85			751	
5BA-MXPB10	[YARIS CROSS]		180	with AHS
5BA-MXPB15			74	
6AA-MXPJ10			1,841	=
6AA-MXPJ15			691	
ZAA-XEAM10	[bZ4X]		75	
ZAA-YEAM15			32	
5BA-AAZA20	[NX250]		724	with AHS
5BA-AAZA25			137	
5BA-TAZA25	[NX350]		432	
6AA-AAZH20	[NX350h]		4,729	
6AA-AAZH25			1,970	1
6LA-AAZH26	[NX450h+]		948	

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF	NOTE
	NAME	RECALLED	VEHICLE	
ZAA-XEAM10X	[SOLTERRA]	2023	18	
ZAA-YEAM15X			178	
		TOTAL	24,767	

The affected parts shipped as repair parts, and could possibility the vehicles equipped with them.

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF	NOTE
	NAME	RECALLED	VEHICLE	
6BA-MXUA80	[HARRIER]	2023	8	with AHS
6AA-AXUH80			8	
6AA-AXUH85			3	
6LA-AXUP85			1	
5BA-MXPB10	[YARIS CROSS]	2020-2021	3	
5BA-MXPB15			2	
6AA-MXPJ10		2020-2023	7	
6AA-MXPJ15	_		3	
5BA-AAZA20	[NX250]	2023	1	
5BA-TAZA25	[NX350]	2022	3	
6AA-AAZH20	[NX350h]	2022-2023	2	
6AA-AAZH25	1	2023	3	
6LA-AAZH26	[NX450h+]	2022	1	
	•	TOTAL	45	

The affected parts shipped as repair parts, and could possibility the vehicles equipped with them.

PARTS NAME	PARTS NO.	SHIPMENT YEAR	NUMBER OF PARTS	NOTE
Headlamp unit ASSY Right	81145-52N30	2003	32	[YARIS CROSS]
	81145-42C90		4	[bZ4X]
Headlamp unit ASSY Left	81185-48J10		189	[HARRIER]
	81185-52N30		35	[YARIS CROSS]
	81185-42C90		6	[bZ4X]
		TOTAL		266