

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5579	DATE	December 6, 2024
MANUFACTURER	KUBOTA Corporation		
DESCRIPTION OF DEFECT	About the device transmits power to the running part, the dimensional accuracy of some of the tension bolt components that apply tension to the running belt was inappropriate. Because of this problem, vibrations and shocks caused by machine operation can repeatedly apply stress to the interference part, and in the worst case, the tension bolt can break, causing the running belt to lose tension and making the machine unable to run.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDP-C523	DR595	9/8/2018～19/10/2023	610
YDR-C615	DR6130	5/7/2018～17/10/2023	2265
YDR-C701	DR7130	8/6/2022～10/10/2023	94
		TOTAL	2969